

 EPA Potential Hazardous Waste Site Identification		Cerclis Site ID Number: TXN000606965
Region 6		
Note: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.		
A. Site Name Circle Court Ground Water	B. Location Identifier - (Lat/Lon or exact Street #) 117 Circle Ct.	
C. City Weatherford	D. State Texas	E. Zip Code 76087
G. Owner/Operator (if known) Name: unknown		I. Telephone Number
<input type="checkbox"/> Federal <input type="checkbox"/> State <input type="checkbox"/> County <input type="checkbox"/> Municipal <input type="checkbox"/> Private <input checked="" type="checkbox"/> Unknown		
1. Site Description Ground water contamination from an unidentified source.		
J. How identified (i.e. Citizen's complaints, OSHA citations, etc.) Routine drinking water sampling identified trichloroethene (TCE) in a municipal supply well operated by the Willow Park.		K. Date Identified 05/04/2007
L. Summary of Potential or Known Problem TCE was detected in a municipal supply well at concentrations above the MCL.		
M. Preparer Information 1. Name Kendrick, Bret	2. Telephone 214.665.2240	3. Date 01/26/2009
EPA Form 2070-8 (5-80)		



872536